From: INAHARA Jill
To: McClintock, Katie
Subject: 50 tpy furnace

Date: Thursday, March 31, 2016 1:19:05 PM

Hi Katie,

I'm being lazy and not looking in the Federal Register.....plus I don't have time. :o(

Do you know where the 50 tpy furnace applicability comes from? How did EPA arrive at that number? We are getting questions about why we chose 10 tpy for the whole facility.

Thanks!

Jill

§63.11449 What parts of my plant does this subpart cover?

- (a) This subpart applies to each existing or new affected glass melting furnace that is located at a glass manufacturing facility and satisfies the requirements specified in paragraphs (a)(1) through (3) of this section.
- (1) The furnace is a continuous furnace, as defined in §63.11459.
- (2) The furnace is charged with compounds of one or more glass manufacturing metal HAP as raw materials.
- (3) The furnace is used to produce glass, which contains one or more of the glass manufacturing metal HAP as raw materials, at a rate of at least 45 Mg/yr (50 tpy).